



RELATÓRIO FOTOGRAFICO

**RECUPERAÇÃO DE CALÇAMENTO DA RODOVIA GUMERCINO MOURA NUNES
E ESTRADA FAZENDA VILA CESAR, ALTO MUTUM PRETO**

MUNICÍPIO DE BAIXO GUANDU

Rodovia Gumericino Moura Nunes

3,5x1,5m



1,0x0,5m



2,0x1,0m



7,0x1,0m



1,0x1,0m



3,0x1,0m




8,0x1,5m



2,0x2,0m



5,0x1,0m



5,0x2,0m




2,0x1,0m




4,0x4,0m



1,5x0,5m



4,0x0,5m



2,0x4,0m



0,5x8,0m



2,0x1,0m



6,0x1,5m



4,0x1,5m



5,0x1,5m



2,0x1,0m



6,0x2,0m



10,0x0,5m



4,0x4,0m



6,0x4,0m




3,0x5,0m



2,0x3,0m



1,0x1,0m



3,0x2,0m



3,0x0,5m



3,0x6,0m



1,0x3,0m



15,0x1,5m



1,0x3,0m



1,5x8,0m



1,0x1,0m



11,0x1,0m



12,0x1,5m



10,0x1,0m



10,0x0,5m



0,5x4,0m



4,0x4,0m



8,0x0,5m



2,0x2,0m



2,0x0,5m



10,0x3,0m



11,0x1,0m



1,0x7,0m



6,0x4,0m



5,0x2,0m



7,0x1,5m



5,0x3,0m



2,0x3,0m



2,0x2,0m



2,0x1,0m



7,0x3,0m



12,0x3,0m



Estrada Fazenda Vila Cesar

5,0x5,0m



16,0x3,0m



1,0x8,0m



10,0x2,0m



3,0x2,0m



4,0x12,0m



4,0x12,0m



14,0x1,5m



8,0x1,5m



9,0x1,0m



13,0x1,0m



3,0x8,0m



3,0x1,5m





